

	L #	Hits	Search Text
1	L1	34547	( dynamometer ) OR (( force load weight stress strain compress\$4 tens\$4 ) near3 ( sens\$4 detect\$4 transducer )).clm.
2	L2	9426	1 and ( substrate support base ).clm.
3	L3	88	2 and ( micromechanical )
4	L4	44	3 and ( deflect\$4 bend\$4 flex\$4 deform\$4 ).clm.
5	L5	2	4 and ( gauge indicator needle ).clm.
6	L6	9	4 and ( gauge indicator needle )
7	L7	1	6 and ( anchor )
8	L8	81	3 and ( deflect\$4 bend\$4 flex\$4 deform\$4 )
9	L10	3	9 and ( anchor )
10	L9	25	8 and ( gauge indicator needle )